

ENGLISH

THIS SOFTWARE IS ONLY FOR UNITS FROM BATCH 322005 !

Note:

Do NOT disconnect the USB or power during update!

Problem solved:

Android Mirrorlink 2-way control in wireless mode